


1	DESCRIPTION	MATERIAL	FINISH
	BODY	BRASS	GOLD PLATED
	INSULATOR	PTFE / TEFLON	N/A
	CENTER CONTACT / PIN	BERYLLIUM COPPER	GOLD PLATED
	FERRULE	ANNEALED COPPER	GOLD PLATED




TERMINATION

CENTRE CONTACT: SOLDER

FERRULE: 3.25mm A/F Crimp Hex

COAX CABLE ASSEMBLY

- 1. STRIP CABLE TO THE DIMENSIONS SHOWN ABOVE TAKING CARE NOT TO CUT INTO THE BRAID OR DIELECTRIC BEYOND THE REQUIRED POINTS.
- CAREFULLY PLACE A PIECE OF HEAT SHRINK SLEEVE THEN FERRULE OVER THE CABLE JACKET, THEN SOLDER THE CONTACT ON TO THE CENTER CONDUCTOR OF THE CABLE.



3. CAREFULLY FAN THE BRAID OUTWARDS SO THAT WHEN SUB ASSEMBLY IS INSERTED INTO THE CONNECTOR BODY AND CENTER CONTACT IS CORRECTLY SEATED IN POSITION ALL THE BRAID LAYS EXTERNAL TO THE CONNECTOR.



4. FINALLY SLIDE THE FERRULE DOWN CABLE AND OVER THE BRAID MAKING SURE IT SITS TIGHT AGAINST THE CONNECTOR BODY THEN CRIMP USING A 3.25MM A/F HEX, SLIDE HEAT SHRINK INTO PLACE AND SHRINK.



ISSUE:	А	SMA Crimp Jack	
DIM:	mm		
		Cable Group - RG174	
		PART No: B5140-J1NN-301-100G	
DATE:	09/04/09		



